

Maintenance Instructions: **DuraGuard**

APPLICATION INSTRUCTIONS FOR DURAGUARD:

NOTE: All previous versions of DuraGuard and other anti-static floor finishes must be removed with CleanStrip Finish Stripper prior to the application of DuraGuard.

Floor surfaces should be 60o F or warmer and in relative humidity conditions between 40-60%. Remove old finish with CleanStrip. Follow directions on stripper label for application. Two coats of DuraGuard are recommended for static dissipative or conductive tiles.

Re-coating of existing finish: Sweep the floor to remove any loose dirt or dust. Wash the floor with ProtectOHM to remove dirt and soil. Apply thin even coats, allowing 1 to 2 hours between coats, depending on humidity conditions. The frequency of refinishing will vary depending on the efficacy of the maintenance program and environmental conditions.

Routine maintenance: Floor surfaces should be swept with an untreated mop daily. DuraGuard should be damp mopped only with ProtectOHM regularly to remove soil, salt, and film deposits, which can degrade the coating's static dissipative properties and gloss. Spray buffing or high-speed burnishing with a soft white polishing pad and DuraGloss is recommended to maintain optimum appearance and static dissipating properties. Do not buff or burnish any sooner than 5 days after the last coat of DuraGuard is applied.

For optimum results do not apply during excessively humid conditions (>60% RH) and do not dry buff or dry burnish.